


■ IGBT Measurement Methods

1. Use black probe to DC (+1 +2) and red probe to R、S、T、U、V、W, measure the clockwise of bias voltage value is about 0.4.



■ IGBT Measurement Methods

1. Use red probe to DC --(--) and black probe to R、S、T、U、V、W, measure the clockwise of bias voltage value is about 0.4.

